


LBP7110Cw 以 USB 連線連接印表機之驅動程式步驟 (以 MAC OSX 10.10 作示範)
The Driver installation procedure for LBP7110Cw (Via USB)(MAC OSX 10.10 as sample)


****注意: 安裝驅動程式前請勿接駁 USB 線，以免系統發生錯誤****

**** Please don't plug the USB cable until the driver asked to do so****


1. 到佳能網站 <https://hk.canon/en/support>，選擇相關的印表機型號及下載印表機的驅動程式 - UFTRII LT Printer Driver
(Go to: <https://hk.canon/en/support> , select related printer model, then download the printer driver - UFTRII LT Printer Driver)
2. 開啟下載檔案「UFTRII LT Printer Driver」，進入「SFP」文件夾(Open “UFTRII LT Printer Driver”，then open “SFP”)




3. 開啟“UFRII_LT_***.pkg”文件開始安裝設定 (Double Click / Open “UFRII_LT_***.pkg”)




4. 按「Continue」(Choose “Continue”)




5. 按「Continue」(Choose “Continue”)




6. 如出現以下畫面，按「Agree」 (Choose “Agree”)



7. 按「Install」 (Choose “Install”)



8. 按「Close」 (Choose “Close”)




9. 完成安裝驅動程式後需新增印表機，先開啟印表機及以 USB 電纜線連接，到「系統偏好設定 (System Preference)」，選「印表機與掃描器 (Printers & Scanners)」 (Turn on printer and connect with USB cable, go to “System Preference”, then open “Printers & Scanners”)



10. 選取左下角「+」按鈕，選「加入印表機或掃描器（Add Printer or Scanner）」（Click “+”, then choose “Add Printer or Scanner”）




11. 名稱選擇「Canon LBP7100Cw」，種類「Bonjour」，確認「使用（Use）」為「Canon LBP7100C/7110C」，然後按「加入（Add）」（“Name” chooses “Canon LBP7100Cw”, “Kind” chooses “Bonjour”. After you confirm “Use” is “Canon LBP7100C/7110C”, then choose “Add”）




*** 如「使用 (Use)」部份不是「Canon LBP7110***」，請按以下步驟設定**
(** If “Use” is not “Canon LBP7110***”, please reference the steps below)**


- a) 請如下圖打開「使用(Use)」的選單，選 Select Software (Open “Use”, then choose “Select Software”)



- b) 輸入 7110 以搜尋「Canon LBP7100C/7110C」(type “7110”, then choose “Canon LBP7100C/7110C”)



12. 加入完成 (Finish)



-完-

-End-