## <u>在 Windows 以 USB 接駁安裝 LiDE 300 驅動程式步驟 (以 Windows 10 示範)</u> LiDE 300 scanner driver Installation Guide for Windows via USB (Demo with Windows 10)

\*\*注意: 安裝驅動程式前請勿接駁 USB 線,以免系統發生錯誤\*\* \*\* Please don't plug the USB cable until the driver asked to do so\*\*

下載及安裝步驟

Driver download and installation procedure

 點擊以下連結下載有關之驅動程式: <u>http://support-hk.canon-asia.com/contents/HK/TC/0100963601.html</u>

Click below link to download printer driver: http://support-hk.canon-asia.com/contents/HK/EN/0100963601.html

- 按以上網頁內的"Download Now",下載完成後開啟該檔案安裝 Click "Download Now" in the webpage above, and open the file after download completed
- 3. 按"下一步"

## Click "Next"



4. 選擇"亞洲",按"下一步"

Select "Asia", and then click "Next"

選擇居住地		$\times$
	選擇居住地,然後按一下[下一步]。	
	居住地(P): [美國,加拿大,拉丁美洲	
X BAR	歐洲,中東,非洲 亞洲 太平洋地區	
1.		
	<上一步(B) 下一步(N) > 取消	

## 5. 按"是"

Click "Yes"

	以下許可協定。	
終端使用者授權合約		^
注意:在安裝本官方授權軟體	豐前,請您閱讀本文件。	
本使用授權合約是您(個人或) 約」),是關於(i)隨同本合約 更新(統稱「軟體」),(ii)軟體 料或印表機的韌體更新(簡稱 體及其更新線上提供用於列印 (本軟體除外)(簡稱「內容資料	實體)與 Canon Inc. 之間的授權合約(簡稱「各 是供給您的軟體程式、相關的電子或線上手 或 Canon 噴墨印表機(簡稱「印表機」)的其 「資料更新」),及(iii)隨同本合約提供或使 口的數位格式之文字、影像、圖示和其他視 斗」)的合約。以後提及的軟體和內容資料各	→ 一 一 及其 → 一 一 及其 ↓ 他 資 用 該 軟 一 用 該 軟 ・ 一 一 節 稱 ◆ 一
	如按一下[否], 掃描器驅動程式的安裝將被	皮取消。
如果接受協定,按一下[是]。		

6. 正在註冊印表機驅動程式,請稍候

Registering the driver, please wait a moment

安裝			
正在	註冊掃描器	區動程式	
2. b.			

將 USB 連接電腦及掃描機,並等待電腦偵測及安裝掃描驅動程式,請稍候
Connect the scanner and the computer with USB cable. Wait until scanner is detected



## 8. 安裝完成,按「完成」

Driver install completed, and then click "Finish"



-完--End-