



CP1200 以USB連線連接印表機安裝驅動程式步驟 (以Win 8.1 作示範)
The driver installation procedure for CP1200 (Via USB)(Win 8.1 as example)

****注意: 安裝驅動程式前請勿接駁 USB 線，以免系統發生錯誤****
**** Please don't plug the USB cable until the setup program asked to do so**


1. 到佳能網站 <http://support-hk.canon-asia.com/>，選擇相關的印表機型號及下載印表機的驅動程式
(Go to: <http://support-hk.canon-asia.com/> , select related printer model, then download the printer driver)
2. 下載的文件「cp1200-***.zip」以壓縮檔檔案保存在指定的文件夾中，打開壓縮檔檔案。(A downloaded zip file “cp1200-***.zip” will be saved at specified location, then open the zip file.)




3. 開啟“cp1200-***.exe” (Open “cp1200-***.exe”)




4. 按「Next>」 (Click “Next>”)




5. 選「Asia」，按「Next>」 (Choose "Asia", and then click "Next>")




6. 按「Yes」 (Click "Yes")




7. 選「Use with a USB Connection」，按「Next>」 (Choose “Use with a USB Connection”, and then click “Next>”)



8. 以 USB 電纜線接駁打印機及電腦，然後開啟打印機 (connect printer and computer with the USB cable, and then turn on the printer)



9. 按「Finish」 (Click “Finish”)



-完-
-End-