

透過 USB 連接安裝 LBP841Cdn 印表機的驅動程式步驟 (以 Win 10 作示範)  
LBP841Cdn printer driver Installation Guide via USB connection (Win 10 as example)

**\*\*注意: 安裝驅動程式前請勿接駁 USB 線，以免系統發生錯誤\*\***

**\*\* Please don't plug the USB cable until the driver asked to do so**

1. 到佳能網站 <https://hk.canon/en/support/imageCLASS%20LBP841Cdn/model>


下載印表機的驅動程式 - UFR II Printer Driver Vxx.xx

Go to: <https://hk.canon/en/support/imageCLASS%20LBP841Cdn/model>

Download the printer driver - UFR II Printer Driver Vxx.xx


2. 下載的文件以自解壓縮檔檔案 (.exe 格式) 保存在指定的文件夾中

The self extractor file (.exe format) is saved to specified folder




3. 打開「UFR11\_Driver\_\*\*\*.exe」檔案。將在同一文件夾中創建新文件夾，如打開文件解壓縮時出現「使用者帳戶控制」選項，按「是」，打開「UFR11\_Driver\_\*\*\*」文件夾

Open "UFR11\_Driver\_\*\*\*.exe" file, a new folder will be created. If "User Account Control" window shows up, click "Yes", and open "UFR11\_Driver\_\*\*\*" file folder




4. 開啓“Setup.exe”檔案


Open "Setup.exe" file




5. 按「Yes」  
Click “Yes”



6. 選「USB Connection」，按「Next >」  
Choose “USB Connection”, and click “Next >”



7. 按「是(Y)」  
Click “Yes(Y)”



8. 以 USB 線接駁印表機及電腦，然後開啟印表機  
Connect printer and computer with the USB cable, and then turn on the printer

### USB Connection

The diagram shows three steps for connecting a printer to a computer via USB:

1. Connect the USB cable to the computer. (An orange arrow points from the USB cable to the computer's USB port.)
2. Connect the USB cable to the printer. (An orange arrow points from the USB cable to the printer's USB port.)
3. Turn on the printer. (A green power button icon is shown next to the printer.)

Follow the steps below to install the printer driver:

Status:


1. Connect the USB cable to the computer.
2. Connect the USB cable to the printer.
3. If the printer power is off, turn on the printer. The printer will be recognized automatically and installation of printer drivers will start.

If the printer is not automatically recognized even with the USB cable connected, disconnect the cable from the printer after turning off the printer, and then connect the cable again.

Progress bar: A green bar is shown on the left side of a progress bar.

Skip

9. 安裝完成，建議別選「Restart My Computer Now」，按「Restart」重新開機  
Installation is completed. We recommend to choose “Restart My Computer Now”, click “Restart” to reboot computer



-完-  
-End-